# 消 防 處 牌 照 及 審 批 總 區



## FIRE SERVICES DEPARTMENT LICENSING AND CERTIFICATION COMMAND

Fire Services Headquarters Building, 5/F, No.1 Hong Chong Road, Tsim Sha Tsui East, Kowloon, Hong Kong

#### 香港九龍 尖沙咀東部康莊道1號5樓 消防總部大廈

本處檔號 Our Ref.: (3) in L/M(2) in FP(LC) 314/07

來函檔號 Your Ref.:

圖文傳真 Fax: 852 - 2723 2197 電 話 Tel No.: 852 - 2733 7619

電子郵件 E-mail: lcpolic2@hkfsd.gov.hk 4 October 2011

To: Registered Fire Service Installation Contractors

Dear Sir/ Madam,

#### **Certificate of Fire Service Installations and Equipment (FS 251)**

This letter serves to promulgate a set of guidelines for the observation of registered fire service installation contractors (RFSIC) on submission of Certificates of Fire Service Installations and Equipment (FS251).

You are well aware that pursuant to regulation 9 of the Fire Service (Installations and Equipment) Regulations, Chapter 95B, Laws of Hong Kong, whenever an RFSIC installs, maintains, repairs or inspects any fire service installation or equipment (FSI) in any premises, he shall within 14 days after completion of the work issue to the person on whose instructions the work was undertaken a certificate and forward a copy thereof to the Director of Fire Services. Against this background, all copies of FS25l completed by RFSIC are either handed to the Fire Services officers on site or forwarded to the Fire Service Installations Task Force (FSITF) of this Department according to the prevailing practice.

With a view to streamlining the procedures and enhancing efficiency, agreement has been made in a recent liaison meeting between the Association of Registered Fire Service Installation Contractors of Hong Kong Limited and the Fire Services Department (FSD) that copies of the completed FS25l should be forwarded to the respective office of the FSD by the concerned RFSIC in accordance with the following schedule effective on 15.10.2011. A list of the addresses of the respective offices of FSD is at **Appendix A**.

#### (i) Regional Office (RO)

All work pertain to the FSI of licensed/registered premises only, e.g. fire extinguisher, exit signs, and self-contained emergency lighting system. However, if the work cover the FSI serving both the building and the licensed/registered premises, e.g. sprinkler system, and fire hydrant and hose reel system, a self-certified photocopy of the relevant FS251 in addition to the one to FSITF, should be forwarded to the respective RO direct. The various types of licensed/registered premises are listed in **Appendix B**.

#### (ii) Dangerous Goods Division (DGD)

All work pertain to the FSI of Dangerous Goods (DG) stores and DG vehicles. However, if the work cover the FSI serving both the building and the DG stores, e.g. sprinkler system, a self-certified photocopy of the relevant FS251 in addition to the one to FSITF, should be forwarded to the DGD direct.

(iii) Fire Service Installations Task Force (FSITF)All work pertain to FSI provided in building or premises other than the above.

Please note that the above arrangements do not preclude RFSIC handing copies of FS251 to officers of this Department during their inspections.

Further, RFSICs are also required to quote as far as practicable the serial number of the previous FS251 describing the corresponding defective FSI item(s) which were reportedly repaired in Part 2 of the FS251 now submitted. A sample of the FS251 to this effect is attached at **Appendix C** for your ease of reference.

If you have any queries pertaining to the above arrangement, please feel free to contact Divisional Officer (FSITF) at telephone number 2733 7879.

Yours faithfully,

(LAU Mun-ming) for Director of Fire Services

#### Addresses of the respective offices of FSD

#### 1. Hong Kong Regional Office

M/F, Sheung Wan Fire Station, 2 Western Fire Services Street, Sheung Wan, HK

#### 2. Kowloon West Sub-regional Office

6/F, Tsim Sha Tsui Fire Station Complex, 333 Canton Road, Kowloon

#### 3. Kowloon East Sub-regional Office

Room 403, 4/F, West Wing, Tsim Sha Tsui Fire Station Complex, 333 Canton Road, Kowloon

#### 4. New Territories Regional Office

Room 402, 4/F, West Wing, Tsim Sha Tsui Fire Station Complex, 333 Canton Road, Kowloon

#### 5. <u>Dangerous Goods Division</u>

4/F, Fire Services Department Kwai Chung Office Building, 86 Hing Shing Road, Kwai Chung, New Territories

#### 6. Fire Service Installations Task Force

4/F, North Wing, Fire Services Headquarters Building,1 Hong Chong Road, Kowloon

#### Appendix B

### <u>List of Licensed and Registered Premises</u> <u>handled by the Regional Offices</u>

- 1. General Restaurant
- 2. Light Refreshment Restaurant
- 3. Factory Canteen
- 4. Food Factory
- 5. Bakery
- 6. Karaoke Establishment
- 7. Dancing School
- 8. Public Dance Hall
- Places of public entertainment such as theatre / cinema, amusement ride, etc
- 10. Billiard Establishment
- 11. Bowling Alley
- 12. Skating rink
- 13. Massage Establishment
- 14. Non-designed School
- Non-exempted Premises for conducting Non-localHigher and Professional Education Courses
- 16. Child Care Centre
- 17. Drug Dependent Persons Treatment and Rehabilitation Centre

FSD Ref.: 消防庭機能

### A 5521901

# FIRE SERVICE (INSTALLATIONS AND EQUIPMENT) REGULATIONS 消防(裝置及設備)規例 (Regulation 9(1)) (第九條 (1) 款) CERTIFICATE OF FIRE SERVICE INSTALLATIONS AND EQUIPMENT 消防裝置及設備證書

Name of 顧客姓名	Client: Tai Ma	n International			
Name of Building: 樓字名稱 Street No/Town Lot: 門牌號數/市地段		an House			
		-	Street/Road/Estate Name: 街道/屋苑名稱	Tai Man Street	
Nock: 座	2	District 分區	Tsuen Wan	Area: □HK □ 地區 □香港 □	K V NT
	Building 樓字類型:	In sec	ercial 樹葉 Domestic 住宅 Cor ordance with Regulation ((b) of Pine Service (Cestallar nest which is installed in any premises shall have such	in and Continued Control of	a 1940 Fif Institutional
第	一部只適用於年檢	事項 120	P由一名莊青本鄉開始至新等域的教皇或皇皇	八篇(b) 版、國有資源在任何國所內的任 至少一次。	行所的自己求政会的人, 包包
1-341	Type of FSI 装置策型	Location(s)位置	Comment on Condition 狀況評論	Completion Date 完成日期 (DDAMAYY)	Next Due Date 下次到第日(DDMM)
			NIL	1 1	
			NIL	1	
				1 1	*
nt 2 第		50000 7	ng / Inspection works 装置尺	裝/修理/檢查工作	
1-34)	Type of PSI 装置模型	Location(s)(立置	Nature of Work Carried out \$42277	Comment on Condition (A)	Completion Date 完成日製のCASSYY
	2 x 9 Litres Foam	10/F	To refill and inspect	Conforms with FSD	6.9.2011
	Type F.E.			requirements	(defect FS251
					No: A320154)
	B (1)				
1.3	8				
4 2 80					
に3 第 (1-34)	三部 Defects 損壞事項 Type of FSI 裝置類型	Location(s)(†)	Outstanding Defects 未修練點	Comment on Defe	ets demonstrate
139	7		NIL		
				2	
13		Ŧ.			
					196 530
ing order i	tified that the above installations/equi in accordance with the Codes of Pra Inspection, Testing and Maintenance	ctice for Minimum Fire S of Installations and Equipm	iervice Installations and Signatur	0:	for PSD use only
e by the D	Director of Fire Services. Defects are 臣明以上之濟防裝置及数	listed in Part 3.			$=$ $ $ $\Box$
方藏藏县	長不醇公佈的最低限度之 差測試及保養守則的規格。	消防裝置及投循守	财典模量及 FSD/RC N		Inspected
	音涉及年後學問	. 电温比较:	Company Nan	Tai Man Fire Eng. C	
全所當民意以保育防息人員查核 This catellities should be deployed a procedure for PRP's impossible F any small analysis man be involved.  White Elife				) to 4114154 = 12.12154	公司 Kayin
(Rev. 11/3	for PRO's Impacts of any and a	includes of the highling or distances most levelued.	PERMITTED AND THE PERMITTED AN		Verified
	(f.)		De	6.9.2011	Vertied